

Figure 6





Figure 7




3000

RATE CONTROL COMMANDS

SUBCLASS	CONDITION	CONDITION	CONDITION	CONDITION	OVERLAY	OVERLAY	OVERLAY	OVERLAY/GNDITION	OVERLAY
FARAMETERS SABORS	R-FOOLE (MIAGNITUDE, DURATION, STYLE, DEADBAND)	Restancion, Duration, STYLE, DEMBAND)	SLV((COEFFICIENT, DURATION, STYLE)	UNDARTION, STYLE)	N_FORCE, (MAGNITUDE, DURATION, DIRECTION)	V-M84E(MAGNITUDE, DURATION, DIRECTION, FREQUENCY, STYLE)	wobble (MAGNITUDE, DURATION, STYLE)	8~F0/CE (MAGNITUDE, DURATION, DIRECTION, BUTTON, AUTOFIRE)	JOUT (MAGNITURE, BURATION, DIRECTION)
FORCE	RESTORING	RESTORING SPRING	SLUGGISH STICK	UNSTABLE	VECTOR	VIBRATION	WOBBLE	BUTTON	100 L

IGURE 9







FIGURE 10b






FIGURE 11 b




FIGURE 11 a




FIGURE 11c




FIGURE 12-




FIGURE 13a




FIGURE 13b

334	POSITION CONTROL COMMANDS 332
FORCE	EXAMPLE OF SERVING AND SERVING PARAMETERS NO 336
VECTOR	P-FACE (MAGNITUDE, DIRECTION)
GROOVE	GROVE (MAGNITUDE, STYLE, SNAP-DISTANCE)
DIVOT	PIVOT (MAGNITUDE, STYLE, SNAP-DISTANCE)
TEXTURE	TEXTURE (MAGNITUDE, DENSITY, STYLE)
BARRIER	X_BARREQMAGNITUDE, LOCATION, SNAP-DISTANCE)
FIELD	行もLD (MAGNITUDE, ORIGIN, SENSE)
PADDLE	PADDE (MASS, GRAVITY, COMPLIANCE, SENSE)
BUTTON	BUTTON (MAGNITUDE, DIRECTION, BUTTON, AUTOFIRE)

FIGURE 14








FIGURE 15












Figure 18




Figure 19




Figure 20a




Figure 20b




Figure 20c




Figure 2





Figure 22






Figure 24





FIGURE 25








FIGURE 27